

Unit 2a, 2b & 2c, Station Road Industrial Estate, Station Road, BAKEWELL, DE45 1GE

Prepared for:

St Johns Abingdon SSAS C/O D Thompson TAG Wealth Management Riverdale 89 Graham Road Sheffield South Yorkshire S10 3GP


Report Reference: SAS_143499645_1_1

Report Date: 19-OCT-2017

Customer Reference: Beauchamp

National Grid Reference: 422230 369010

Site Area: 640 m²





If you have any questions on the contents of this Report please contact ENVI Data

Telephone: 0114 263 2418 Fax: 0114 263 2419

Email: reports@envidata.com





Professional Opinion on environmental risk

PASSED

The Sitecheck report dated 19-OCT-2017 and reference SAS_143499645_1_1 for Unit 2a, 2b & 2c, Station Road Industrial Estate, Station Road, BAKEWELL, DE45 1GE has examined the sources of potential contamination in terms of historical land use, environmental data and current land uses where known.

The report has highlighted the presence of Furnaces on or within 25m of the site boundary.

INTRODUCTION

This professional opinion determines the level of environmental risk, as to whether a pollutant linkage exists which is created when there is a source of contamination, a pathway for it to travel along and receptors, which may be harmed. This risk-based approach underpins the government approach to contaminated land. If a pollutant linkage exists the property may be regarded by the local authority as being "Contaminated Land" for the purposes of Part 2A of the Environmental Protection Act 1990.

In completing this report, Argyll Environmental has undertaken a review of data made available to it. No site inspection, further enquiries or investigation of surface or ground conditions has been carried out by Argyll Environmental. No information as to the age, value and type of property has been made available. It is important to note that it is not known by Argyll Environmental for what purpose the report has been commissioned.

FACTORS AFFECTING THIS PROPERTY

Potential Sources:

A review of historical mapping has revealed the following historical or current potentially contaminative uses of concern on site: railways (1879) and buildings associated with an industrial estate (1984).

From contemporary trade directory entries it would appear that companies associated with high risk contaminative uses are located on or within 25 metres of the site. Although this may identify current occupiers no details are available to confirm whether or not potentially contaminative operations are taking place.

Potential Pathways:

- Direct human contact with soil (and water).
- Contamination transport to shallow groundwater.
- Contamination transport to deep groundwater.



Professional Opinion on environmental risk

Potential Receptors:

The property itself, surrounding properties and their respective occupants may be considered as receptors. Buildings and people can suffer harm by definition of Part 2A of the Environmental Protection Act 1990.

Current Ordnance Survey mapping indicates residential dwellings and woodland within 25 metres of the site boundary.

The groundwater vulnerability map, Sheet 17 Derbyshire & North Staffordshire, has revealed that the site is located above a Minor Aquifer (Variably permeable).

Although minor aquifers seldom produce large quantities of water for abstraction they may be important for local supplies and supplying base flow to rivers.

CONCLUSIONS:

In the professional opinion of Argyll Environmental, the level of risk associated with the information disclosed in the associated Sitecheck Assess report:

- 1) is unlikely to have an adverse effect on the value of the property, and
- 2) is not such that the property would be designated "contaminated land" within the meaning of Part IIA of the Environmental Protection Act 1990.

OTHER ENVIRONMENTAL FACTORS:

In this case the following environmental factors have been identified which a client may wish to be investigated before proceeding further:

An area affected by radon An area of Mining Instability An area of Occasional Non-coal Mining Hazard An area of Subsidence Hazard Potential

Please refer to the relevant section in the report for each of the above factors.

Approved by

Argyll Environmental Ltd





Professional Opinion on environmental risk

SOURCES OF ADDITIONAL PROFESSIONAL GUIDANCE:

If the report is for valuation, or investment, or other forms of lending decision making there may be issues arising from the current occupation, which need to be examined. The Royal Institution of Chartered Surveyors has provided guidance with respect to such matters and specific reference should be made to the guidance note 'Contamination, the environment and sustainability - Implications for chartered surveyors and their clients' published April 2010. This guidance note is referred to in UKGN1.1 paragraph 2.2 of the RICS Valuation Standards (6th Edition) (The "Red Book").

It is recommended that the client reviews the outputs of any valuation report, which should include a Property Observation Checklist, contained at Appendix A for commercial property or Appendix B for rural property in the Royal Institution of Chartered Surveyors guidance note 'Contamination, the environment and sustainability - Implications for chartered surveyors and their clients'. Completion of these checklists does not constitute an environmental assessment for the purposes of Professional Indemnity Insurance where many surveyors are unlikely to have appropriate indemnity cover. Any contamination, which is observed on the site by the surveyor during the normal course of their inspection, can also be recorded.

If the property is let, the landlord or the tenant (as appropriate) should take legal advice as to whether the covenants in the lease constitute legal or financial burdens. The Law Society's "Environmental Law Handbook-6th Edition" provides valuable assistance.

In leases with no express covenants dealing with environmental matters, lawyers and surveyors need to be aware of the extent to which the repairing of covenants can be applied and, when advising tenant clients in particular, will need to draw attention to the client's obligations to comply with enacted legislation.

Should contamination have been observed on site a suitably qualified, insured and experienced professional, preferably with the Specialist in Land Condition (SiLC) accreditation, should quantify whether this could give rise to an action by a regulator or any other party. A suitable management plan for action incorporated in a Land Quality Statement in accordance with RICS guidance should be put in place and appropriate matters taken up with the tenant / occupier.

In terms of development this report should be seen as a precursor to a thorough investigation of the property for planning control purposes. The DTI funded guidance published by the Construction Industry Research and Information Association (CIRIA) Brownfields-managing the development of previously developed land-a clients guide may be a useful starting point.

This professional opinion forms part of the Sitecheck Assess report and is subject to Landmark Information Group's Terms and Conditions of Business in force from time to time. Further information on the methodology and the datasets examined in this professional opinion is included in the Sitecheck Asses Practitioner Guide.

Report Sections and Details

Page

2

Summary of Site

This section comprises contaminant, pathway and receptor information found on site. Other factors which may affect the site are also included.

Aerial Photo

The aerial photo gives an overall view of the area. The smaller large-scale Ordnance Survey map includes the site boundary and search zone buffer at 500m.

Location Map

The large-scale Ordnance Survey map includes the site boundary and search zone buffer at 500m. The smaller aerial photo also includes the site boundary.

Summary Table 3

This section comprises of a summary table of the information found on site and in its vicinity.

Current Land Use

This section contains a map, which shows current land use features. The following pages detail these features and identify the Reference Number and direction.

Historical Land Use 10

This section contains a map, which shows historical land use features. The following pages detail these features and identify the Reference Number and direction. A table listing all the maps used to source this information is included.

Sensitivity 13

This section contains a map, which shows pathway and receptor features. The following pages detail these features and identify the Reference Number and direction. This section also contains a separate Flood Map and flood details.

Other Factors 17

This section contains information on other factors which may affect the site and its vicinity.

Useful Information 19

This section contains information which may be of use when interpreting the report.

Useful Contacts 20

All textual information is linked by the 'Contact Ref' to this quick reference list of contacts. These contacts may be able to supply additional information or answer any subsequent query relating to that record.

Current Land Use Potentially Contaminative Uses	Page No.	Reference Number (Map ID)
Contemporary Trade Directory Entries		
Taylormade Induction Ltd, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Furnaces, Status: Inactive, Positional Accuracy: Automatically positioned to the address	8	1
Bakewell M O T Centre Ltd, Unit 7, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Mot Testing Centres, Status: Active, Positional Accuracy: Automatically positioned to the address	8	2
T H B Mower Services, Unit 2c, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Lawnmowers & Garden Machinery - Sales & Service, Status: Inactive, Positional Accuracy: Automatically positioned to the address	8	2

Historical Land Use Potentially Contaminative Uses	Page No.	Reference Number (Map ID)
Potentially Contaminative Industrial Uses (Past Land Use)		
Railways, Date of Mapping: 1883 - 1955	11	3

Sensitivity Pathways	Page No.	Reference Number (Map ID)
Groundwater Vulnerability		
Geological Classification: Minor Aquifer (Variably permeable) - These can be fractured or potentially fractured rocks, which do not have a high primary permeability, or other formations of variable permeability including unconsolidated deposits. Although not producing large quantities of water for abstraction, they are important for local supplies and in supplying base flow to rivers, Soil Classification: Soils of Low Leaching Potential - Soils in which pollutants are unlikely to penetrate the soil layer because water movement is largely horizontal or they have large ability to attenuate diffuse pollutants. Lateral flow from these soils contribute to groundwater recharge elsewhere in the catchment, Map Scale: 1:100,000, Map Name: Sheet 17 Derbyshire & North Staffordshire, Contact Ref: 1	15	-

Sensitivity Protected Countryside Areas	Page No.	Reference Number (Map ID)
National Parks		
Peak District, Designation Date: 1st April 1951, Area: 1437831812.8(m2), Contact Ref: 3	16	5

Other Factors Geological	Page No.	Reference Number (Map ID)
Mining Instability		
Risk: Conclusive Metaliferous Mining,	17	-
Non Coal Mining Areas of Great Britain		
Hazard Potential: Highly Unlikely, Contact Ref: 2	17	-
Radon Potential - Radon Affected Areas		
Affected Areas: The property is in an Intermediate probability radon area (5 to 10% of homes are estimated to be at or above the Action Level)., Source: British Geological Survey, National Geoscience Information Service, Contact Ref: 2	17	-
Radon Potential - Radon Protection Measures		
Radon Protection Measures: Basic, Source: British Geological Survey, National Geoscience Information Service, Contact Ref: 2	17	-
Potential for Landslide Ground Stability Hazards		
Hazard Potential: Low, Contact Ref: 2	17	-
Potential for Shrinking or Swelling Clay Ground Stability Hazards		
Hazard Potential: Very Low, Contact Ref: 2	18	-
Potential for Collapsible Ground Stability Hazards		
Hazard Potential: Very Low, Contact Ref: 2	17	-



Unit 2a, 2b & 2c,Station Road Industrial Estate,Station Road,BAKEWELL,DE45 1GE

Grid Reference 422230, 369010


Report Reference SAS_143499645_1_1


Customer Reference

Beauchamp

Size of Site

640 m²





Unit 2a, 2b & 2c,Station Road Industrial Estate,Station Road,BAKEWELL,DE45 1GE

Grid Reference 422230, 369010

Report Reference

SAS_143499645_1_1

Customer Reference

Beauchamp

Size of Site

640 m²



Current Land Use	On Site	0-250m	250- 500m
Contaminants	3	8	8
Waste / Landfill Sites			
BGS Recorded Landfill Sites	0	0	0
Licensed Waste Management Facilities (Landfill Boundaries)	0	0	0
Licensed Waste Management Facilities (Locations)	0	0	0
Local Authority Recorded Landfill Sites	0	0	0
Registered Landfill Sites	0	0	0
Registered Waste Transfer Sites	0	0	0
Registered Waste Treatment or Disposal Sites	0	0	0
Statutory Authorisations			
Local Authority Pollution Prevention and Controls	0	0	0
Contaminated Land Register Entries and Notices	0	0	0
Radioactive Substances Register	0	0	0
Discharge Consents			
Discharge Consents	0	0	2
Water Industry Act Referrals	0	0	0
Industrial Processes			
Integrated Pollution Controls	0	0	0
Integrated Pollution Control Registered Waste Sites	0	0	0
Environmental Permitting Regulations - Industry	0	0	0
Local Authority Integrated Pollution Prevention And Control	0	0	0
Storage of Hazardous Substances			
Control of Major Accident Hazards Sites (COMAH)	0	0	0
Explosive Sites	0	0	0
Notification of Installations Handling Hazardous Substances (NIHHS)	0	0	0
Planning Hazardous Substance Consents	0	0	0
Contraventions			
Local Authority Pollution Prevention and Control Enforcements	0	0	0
Enforcement and Prohibition Notices	0	0	0
Planning Hazardous Substance Enforcements	0	0	0
Prosecutions Relating to Authorised Processes	0	0	0
Prosecutions Relating to Controlled Waters	0	0	0
Substantiated Pollution Incident Register	0	0	0

Current Land Use	On Site	0-250m	250- 500m
Contaminants	3	8	8
Potentially Contaminative Uses			
Contemporary Trade Directory Entries	3	8	6
Fuel Station Entries	0	0	0
Miscellaneous			
BGS Recorded Mineral Sites	0	0	0


Historical Land Use	On Site	0-250m	250- 500m
Contaminants	1	3	8
Potentially Contaminative Uses			
Historical Tanks And Energy Facilities	0	1	1
Potentially Contaminative Industrial Uses (Past Land Use)	1	2	4
Potentially Infilled Land			
Former Marshes	0	0	0
Potentially Infilled Land (Non-Water)	0	0	0
Potentially Infilled Land (Water)	0	0	3

Sensitivity	On Site	0-250m	250- 500m
Pathways and Receptors	2	0	3
Pathways			
Groundwater Vulnerability	1	n/a	n/a
Drift Deposits	0	n/a	n/a
Historical Flood Liabilities	0	0	0
Extreme Flooding from Rivers or Sea without Defences	0	0	n/a
Flooding from Rivers or Sea without Defences	0	0	n/a
Areas Benefiting from Flood Defences	0	0	n/a
Flood Water Storage Areas	0	0	n/a
Flood Defences	0	0	n/a

Sensitivity	On Site	0-250m	250- 500m
Pathways and Receptors	2	0	3
Environmentally Sensitive Receptors			
Areas of Outstanding Natural Beauty	0	0	0
Environmentally Sensitive Areas	0	0	0
Local Nature Reserves	0	0	0
Marine Nature Reserves	0	0	0
National Nature Reserves	0	0	0
Nearest Surface Water Feature	0	0	1
Ramsar Sites	0	0	0
Sites of Special Scientific Interest	0	0	0
Source Protection Zones	0	0	0
Special Areas of Conservation	0	0	0
Special Protection Areas	0	0	0
Water Abstractions	0	0	2
Protected Countryside Areas			
Forest Parks	0	0	0
National Parks	1	0	0
National Scenic Areas	0	0	0

Other Factors	On Site	0-250m	250- 500m
Geological	10	5	0
Brine Compensation Area	0	n/a	n/a
Coal Mining Affected Areas	0	n/a	n/a
Mining Instability	1	2	n/a
Man-Made Mining Cavities	0	0	0
Natural Cavities	0	0	0
Non Coal Mining Areas of Great Britain	1	1	n/a
Radon Potential - Radon Affected Areas	1	n/a	n/a
Radon Potential - Radon Protection Measures	1	n/a	n/a
Potential for Collapsible Ground Stability Hazards	1	0	n/a
Potential for Compressible Ground Stability Hazards	1	0	n/a
Potential for Ground Dissolution Stability Hazards	1	0	n/a
Potential for Landslide Ground Stability Hazards	1	1	n/a
Potential for Running Sand Ground Stability Hazards	1	0	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	1	1	n/a







Contaminants				
Waste / Landfill Sites	Ref No.	Search Buffer	Direction	
Local Authority Landfill Coverage				
Name: Derbyshire Dales District Council, - Has no landfill data to supply, Contact Ref: 4	-	On Site	SE	
Name: Derbyshire County Council, - Had landfill data but passed it to the relevant environment agency, Contact Ref: 5	-	On Site	SE	

Discharge Consents	Ref No.	Search Buffer	Direction
Discharge Consents			
Severn Trent Water Limited, Cso Serving Baslow Road, Baslow Road, Bakewell, Derbyshire, Sewerage Discharge, Reference: T/38/02671/O, Version: 2, Status: Varied by Application - (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995), Positional Accuracy: Located by supplier to within 100m, Contact Ref: 1	-	250-500m	W
Severn Trent Water Limited, Baslow Rd/King St/Nt Church St/S/Of Baslow Road - King Street, North Church Street, Bakewell, Derbyshire, Sewerage Discharge, Reference: T/38/02671/O, Version: 1, Status: Pre National Rivers Authority Legislation where issue date < 01/09/1989, Positional Accuracy: Located by supplier to within 100m, Contact Ref: 1	-	250-500m	W

Potentially Contaminative Uses	Ref No.	Search Buffer	Direction
Contemporary Trade Directory Entries			
Taylormade Induction Ltd, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Furnaces, Status: Inactive, Positional Accuracy: Automatically positioned to the address	1	On Site	NE
Bakewell M O T Centre Ltd, Unit 7, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Mot Testing Centres, Status: Active, Positional Accuracy: Automatically positioned to the address	2	On Site	NE
T H B Mower Services, Unit 2c, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Lawnmowers & Garden Machinery - Sales & Service, Status: Inactive, Positional Accuracy: Automatically positioned to the address	2	On Site	NE
Task Master Cleaning Services Ltd, Unit 4A Station Road Ind Est, Bakewell, Derbyshire, DE45 1GF, Commercial Cleaning Services, Status: Inactive, Positional Accuracy: Manually positioned within the geographical locality	6	0-250m	S
Vantage Waste Management, Vantage House, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Waste Disposal Services, Status: Active, Positional Accuracy: Automatically positioned to the address	7	0-250m	NW
Induction Heating Systems Ltd, Unit 4a, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Foundry Equipment & Supplies, Status: Active, Positional Accuracy: Automatically positioned to the address	7	0-250m	N

Contaminants	-		-
Potentially Contaminative Uses	Ref No.	Search Buffer	Direction
Contemporary Trade Directory Entries			
Vantage Waste Management, Vantage House, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Waste Disposal Services, Status: Inactive, Positional Accuracy: Automatically positioned to the address	7	0-250m	NW
Codel International Ltd, Unit 1a-1c, Station Yard, Station Road, Bakewell, DE45 1GE, Manufacturers, Status: Active, Positional Accuracy: Automatically positioned to the address	8	0-250m	S
Tony Team Ltd, Unit 5, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Waste Disposal Services, Status: Inactive, Positional Accuracy: Automatically positioned to the address	9	0-250m	N
Tony Team, Unit 5, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Waste Processing Machinery, Status: Inactive, Positional Accuracy: Automatically positioned to the address	9	0-250m	N
Tony Team, Unit 6, Station Yard, Station Road, Bakewell, Derbyshire, DE45 1GE, Waste Processing Machinery, Status: Active, Positional Accuracy: Automatically positioned to the address	10	0-250m	NW
Derbyshire Community Health Services N H S Foundation Trust, Baslow Road, Bakewell, DE45 1AD, Hospitals, Status: Active, Positional Accuracy: Automatically positioned to the address	11	250-500m	NW
Derbyshire Community Health Services Nhs Trust, Baslow Road, Bakewell, Derbyshire, DE45 1AD, Hospitals, Status: Inactive, Positional Accuracy: Automatically positioned to the address	11	250-500m	NW
High Peak & Dales Primary Care Trust, Baslow Road, Bakewell, Derbyshire, DE45 1AD, Hospitals, Status: Inactive, Positional Accuracy: Automatically positioned to the address	11	250-500m	NW
Derbyshire County Pct, Baslow Rd, Bakewell, Derbyshire, DE45 1AD, Hospitals, Status: Inactive, Positional Accuracy: Manually positioned to the address or location	11	250-500m	NW
Barbel, Flat 7, Castle Hill, Baslow Road, Bakewell, Derbyshire, DE45 1AA, Catering Equipment, Status: Active, Positional Accuracy: Automatically positioned to the address	-	250-500m	SW
Shape Posture Seating, Rutland Mill, Coombs Road, Bakewell, Derbyshire, DE45 1AQ, Office Furniture & Equipment, Status: Active, Positional Accuracy: Automatically positioned to the address	-	250-500m	SW





Contaminants			
Potentially Contaminative Uses	Ref No.	Search Buffer	Direction
Historical Tanks And Energy Facilities			
Electrical Sub Station Facilities, Scale of Mapping: 1:2,500, Date of Mapping: 1970	12	0-250m	S
Electrical Sub Station Facilities, Scale of Mapping: 1:2,500, Date of Mapping: 1970	-	250-500m	S
Potentially Contaminative Industrial Uses (Past Land Use)			
Railways, Date of Mapping: 1883 - 1955	3	On Site	SE
Railways, Date of Mapping: 1883 - 1955	4	0-250m	NE
Hospitals, Date of Mapping: 1923 - 1974	13	0-250m	NW
Railways, Date of Mapping: 1883 - 1955	14	250-500m	SE
Factory or works - use not specified, Date of Mapping: 1974	-	250-500m	S
Sawmilling, planing & impregnation [i.e. treatment of timber], Date of Mapping: 1923 - 1955	-	250-500m	S
General quarrying, Date of Mapping: 1883 - 1899	-	250-500m	S

Potentially Infilled Land	Ref No.	Search Buffer	Direction
Potentially Infilled Land (Water)			
Unknown Filled Ground (Pond, marsh, river, stream, dock etc), Date of Mapping: 1955	-	250-500m	S
Unknown Filled Ground (Pond, marsh, river, stream, dock etc), Date of Mapping: 1955	-	250-500m	SW
Unknown Filled Ground (Pond, marsh, river, stream, dock etc), Date of Mapping: 1938	-	250-500m	SW

Map	Details
map	Dotailo


The following maps have been analysed for Historical Tanks and Energy Facilities


1:2,500	Mapsheet	Published
Ordnance Survey Plan	SK2268	1970
Ordnance Survey Plan	SK2269	1970

The following maps have been analysed for Potentially Contaminative Uses and Potentially Infilled Land information


1:10,000	Mapsheet	Published
Ordnance Survey Plan	SK26NW	1974
1:10,560	Mapsheet	Published
Derbyshire	023_SE	1883
Derbyshire	023_SE	1899
Derbyshire	023_SE	1923
Derbyshire	023_SE	1938
Ordnance Survey Plan	SK26NW	1955


Flood Map





Sensitivity Map





Pathways and Receptors			
Pathways	Ref No.	Search Buffer	Direction
Groundwater Vulnerability			
Geological Classification: Minor Aquifer (Variably permeable) - These can be fractured or potentially fractured rocks, which do not have a high primary permeability, or other formations of variable permeability including unconsolidated deposits. Although not producing large quantities of water for abstraction, they are important for local supplies and in supplying base flow to rivers, Soil Classification: Soils of Low Leaching Potential - Soils in which pollutants are unlikely to penetrate the soil layer because water movement is largely horizontal or they have large ability to attenuate diffuse pollutants. Lateral flow from these soils contribute to groundwater recharge elsewhere in the catchment, Map Scale: 1:100,000, Map Name: Sheet 17 Derbyshire & North Staffordshire, Contact Ref: 1	-	On Site	SE
Drift Deposits			
None	-		-
Extreme Flooding from Rivers or Sea without Defences			
None	-		-
Flooding from Rivers or Sea without Defences			
None	-		-
Areas Benefiting from Flood Defences			
None	-		-
Flood Water Storage Areas			
None	-		-
Flood Defences			
None	-		-

Environmentally Sensitive Receptors	Ref No.	Search Buffer	Direction
Nearest Surface Water Feature			
Distance: 321m	-	250-500m	W
Water Abstractions			
Bakewell Golf Club, Near Bakewell - Tributary Of River Wye, Abstractions Industrial, Reference: 03/28/39/0097, Permit Version: 100, Authorised Start: 01 April, Authorised End: 31 October, Positional Accuracy: Located by supplier to within 100m, Contact Ref: 1	-	250-500m	E
Christian Residential Homes For The Elderly, Near Bakewell - Tributary Of River Wye, Abstractions Miscellaneous, Reference: 03/28/39/0098, Permit Version: 100, Authorised Start: 01 April, Authorised End: 31 March, Positional Accuracy: Located by supplier to within 10m, Contact Ref: 1	-	250-500m	E

Pathways and Receptors Protected Countryside Areas	Ref No.	Search Buffer	Direction
National Parks			
Peak District, Designation Date: 1st April 1951, Area: 1437831812.8(m2), Contact Ref: 3	5	On Site	SE

Other Factors		
Geological	Search Buffer	Direction
Brine Compensation Area		
No		-
Coal Mining Affected Areas		
In an area which may not be affected by Coal Mining		-
Mining Instability		
Risk: Conclusive Metaliferous Mining,	On Site	SE
Risk: Conclusive Metaliferous Mining,	0-250m	W
Risk: Conclusive Rock Mining,	0-250m	W
Non Coal Mining Areas of Great Britain		
Hazard Potential: Highly Unlikely Contact Ref: 2	On Site	SE
Hazard Potential: Unlikely Contact Ref: 2	0-250m	W
Radon Potential - Radon Affected Areas		
Affected Areas: The property is in an Intermediate probability radon area (5 to 10% of homes are estimated to be at or above the Action Level)., Source: British Geological Survey, National Geoscience Information Service, Contact Ref: 2	On Site	SE
Radon Potential - Radon Protection Measures		
Radon Protection Measures: Basic, Source: British Geological Survey, National Geoscience Information Service, Contact Ref: 2	On Site	SE
Potential for Collapsible Ground Stability Hazards		
Hazard Potential: Very Low, Contact Ref: 2	On Site	SE
Potential for Compressible Ground Stability Hazards		
Hazard Potential: No Hazard, Contact Ref: 2	On Site	SE
Potential for Ground Dissolution Stability Hazards		
Hazard Potential: No Hazard, Contact Ref: 2	On Site	SE
Potential for Landslide Ground Stability Hazards		
Hazard Potential: Low, Contact Ref: 2	On Site	SE
Hazard Potential: High, Contact Ref: 2	0-250m	Е
Potential for Running Sand Ground Stability Hazards		
Hazard Potential: No Hazard, Contact Ref: 2	On Site	SE

Other Factors		
Geological	Search Buffer	Direction
Potential for Shrinking or Swelling Clay Ground Stability Hazards		
Hazard Potential: Very Low, Contact Ref: 2	On Site	SE
Hazard Potential: No Hazard, Contact Ref: 2	0-250m	Е

Registered Landfill Sites

At present no complete national data set exists for landfill site boundaries, therefore a point grid reference, provided by the data supplier, is used for some landfill sites. In certain cases the point grid references supplied provide only an approximate position and can vary from the site entrance to the centre of the site. Where the exact position of the site is unclear, Landmark construct either a 100 metre or 250 metre "buffer" around the point to warn of the possible presence of landfill. The size of this "buffer" relates to the positional accuracy that can be attributed to the site. The "buffer" is shown on the map as an orange cross-hatched circle and is referred to in the map legend as Potential Landfill Buffer. Where actual boundaries are available, the landfill site area is shown on the map as a red diagonal hatched polygon and referred to in the map legend as Registered Landfill Site.

Local Authority Recorded Landfill Sites

Local Authority landfill data are sourced from individual local authorities that were able to provide information on sites operating prior to the introduction of the Control of Pollution Act (COPA) in 1974. Appropriate authorities are listed under Local Authority Landfill Coverage with an indication of whether or not they were able to make landfill data available. Details of any records identified are disclosed. You should be aware that if the local authority 'Had landfill data but passed it to the relevant environment agency' it does not necessarily mean that local authority landfill data is included in our other Landfill datasets. In addition if no data has been made available, for all or part of the search area, you should be aware that a negative response under 'Local Authority Recorded Landfill Sites' does not necessarily confirm that no local authority landfills exist.

Flooding

The Sitecheck report flood map plots all flood related features revealed within the search area as supplied by the relevant environment agency. However, to avoid confusion, the text entry in the body of the report only reveals the detail of the nearest feature in each flood data set. This is also reflected in the summary table where only a single entry is included to indicate the search buffer of the nearest occurrence.

Mining Instability Data

The Mining Instability data was obtained on Licence from Ove Arup + Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such data is to be made without the prior written consent of Ove Arup + Partners Limited. The information and data supplied in the Product are derived from publicly available records and other third party sources and neither Ove Arup + Partners nor Landmark warrant the accuracy or completeness of such information or data.

The information in this Sitecheck Assess Report is derived from a number of statutory and non-statutory sources. While every effort is made to ensure accuracy, Landmark cannot guarantee the accuracy or completeness of such information or data, nor to identify all the factors that may be relevant. If you are a private individual using this report Landmark recommend that you discuss its contents in full with your professional advisor. It is essential to read this report in conjunction with the Product User Guide and your attention is drawn to the scope of the report section within this guide.

The Sitecheck Assess User guide is available free of charge from our website www.sitecheck.co.uk

Landmark Information Group Limited 2011. All Rights Reserved. The copyright on the information and data and its format as contained in this Siteche Assess Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, the Environment Agency/Natural Resources Wales and Natural England and must not be reproduced in whole or in part by photocopying or any other method, except as allowed by Landmark's Terms and Conditions. The Report is supplied under Landmark's Terms and Conditions accepted by the customer. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and/or other Data Providers, whose copyright material has been included in this Report.



















Contact Names and Addresses

1 Environment Agency National Customer Contact Centre (NCCC)

PO Box 544 Templeborough Rotherham S60 1BY Telephone 03708 506 506

enquiries@environment-agency.gov.uk

Please note that the Environment Agency/Natural Resources Wales/SEPA have a charging policy in place for enquiries.

2 British Geological Survey Enquiry Service

British Geological Survey Kingsley Dunham Centre Keyworth Nottingham Nottinghamshire NG12 5GG

enquiries@bgs.ac.uk www.bgs.ac.uk Telephone 0115 936 3143 Fax 0115 936 3276

3 Natural England

County Hall Spetchley Road Worcester WR5 2NP

enquiries@naturalengland.org.uk www.naturalengland.org.uk Telephone 0300 060 3900

Telephone 01629 580580

4 Derbyshire Dales District Council

Town Hall Bath Street Matlock Derby Derbyshire DE4 3NN

Fax 01629 580482

www.derbyshiredales.gov.uk

5 Derbyshire County Council

County Offices Matlock Derbyshire DE4 3AG Telephone 01629 580000 Fax 01629 580119

www.derbyshire.gov.uk

Other Contacts

Institution of Civil Engineering Surveyors

26 Market Street ALTRINCHAM Cheshire WA14 1PF Telephone 0161 928 8074

www.ices.org.uk/ices.asp

The Association of Geotechnical and Geoenvironmental Specialists

Foreham Street 83 Copers Cope Road Beckenham Kent BR3 1NR Telephone 020 86588212

www.ags.org.uk/

The Environmental Auditors Registration Association

Welton House Limekiln Way Lincoln LN2 4US Telephone 01522 540069

www.greenchannel.com/iea/earahome.htm

The Environmental Industries Commission

45 Weymouth Street London W1N 3LD Telephone 020 79351675

www.eic-uk.co.uk/

The Institution of Civil Engineers

One Great George Street Westminster LONDON SW1P 3AA Telephone 0207 222 7722 Fax 0207 222 7500

www.ice.org.uk

The Royal Institution of Chartered Surveyors

12 Great George Street Parliament Square London SW1P 3AD Telephone 020 7222 7000

Telephone 0845 458 5250

www.rics.org.uk/

Argyll Environmental Ltd

1st Floor 98-99 Queens Road Brighton BN1 3XF

Fax 0845 458 5260

info@argyllenviro.com www.argyllenvironmental.com

Landmark Information Group Limited

Legal and Financial Imperium Imperial Way Reading Berkshire RG2 0TD Telephone 0844 844 9966 Fax 0844 844 9980

info@landmarkinfo.co.uk www.landmarkinfo.co.uk





Search Code

IMPORTANT CONSUMER PROTECTION INFORMATION

This search has been produced by Landmark Information Group Ltd, Imperium, Imperial Way, Reading, Berkshire, RG2 0TD. Telephone: 0844 844 9966, Fax No: 0844 844 9980, email: helpdesk@landmark.co.uk which is registered with the Property Codes Compliance Board (PCCB) as a subscriber to the Search Code. The PCCB independently monitors how registered search firms maintain compliance with the Code.

The Search Code:

- Provides protection for homebuyers, sellers, conveyancers and mortgage lenders who rely on the information included in property search reports undertaken by subscribers on residential and commercial property within the United Kingdom.
- Sets out minimum standards which firms compiling and selling search reports have to meet.
- Promotes the best practice and quality standards within the industry for the benefit of consumers and property professionals.
- Enables consumers and property professionals to have confidence in firms which subscribe to the code, their products and services.

By giving you this information, the search firm is confirming that they keep to the principles of the Code. This provides important protection for you.

The Code's core principles

Firms which subscribe to the Code will:

- Display the Code logo prominently on their search reports.
- Act with integrity and carry out work with due skill, care and diligence.
- At all times maintain adequate and appropriate insurance to protect consumers.
- Conduct business in an honest, fair and professional manner.
- Handle complaints speedily and fairly.
- Ensure that all search services comply with the law, registration rules and standards.
- Monitor their compliance with the Code.

COMPLAINTS

If you have a query or complaint about your search, you should raise it directly with the firm, and if appropriate ask for your complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Code.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs or to the PCCB.

TPOs Contact Details:

The Property Ombudsman Scheme Milford House 43-55 Milford Street Salisbury Wiltshire SP1 2BP Tel: 01722 333306

Fax: 01722 332296 Web site: www.tpos.co.uk Email: admin@tpos.co.uk

You can get more information about the PCCB from www.propertycodes.org.uk.

PLEASE ASK YOUR SEARCH PROVIDER IF YOU WOULD LIKE A COPY OF THE SEARCH CODE





Search Code

COMPLAINTS PROCEDURE

If you want to make a complaint, we will:

- Acknowledge it within 5 working days of its receipt.
- Normally deal with it fully and provide a final response, in writing, within 20 working days of receipt.
- Keep you informed by letter, telephone or e-mail, as you prefer, if we need more time.
- Provide a final response, in writing, at the latest within 40 working days of receipt.
- Liaise, at your request, with anyone acting formally on your behalf.

Complaints should be sent to:

Head of Customer Relations Landmark Information Group Ltd Landmark UK Property Imperium Imperial Way Reading RG2 0TD

Telephone: 0844 844 9966

E-mail: helpdesk@landmark.co.uk

Fax: 0844 844 9980

If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman Scheme (TPOs): Tel: 01722 333306, E-mail: admin@tpos.co.uk.

We will co-operate fully with the Ombudsman during an investigation and comply with his final decision.

LANDMARK STANDARD TERMS & CONDITIONS

Full Terms and Conditions can be found on the following link:

http://www.landmarkinfo.co.uk/Terms/Show/515